









LUMEN TECHNOLOGIES SOLUTION





Company Reg No. 002325445-K
 No. 9 JALAN 30,
 KAMPUNG CHERAS BARU,
 56100 KUALA LUMPUR, MALAYSIA.
 TEL: 012-235 3359 E-MAIL: lumentechs@gmail.com

COMPLETED JOB DETAILS YEAR 2022					
No.	Client Name	Service Job Location	Job Scope	Qty	End User
145	 PO No. A1000033814 PO DATE: 17/FEB/22	JOB DONE: MIR VALVE PREMISES JOB COMPLETION DATE: 20- FEB-2022	 Material: Size & Rating: Finding: ENP affected corroded are on balls	3 Nos	
146	 PRESTON SHIPYARD SDN BHD PO No. PO/PSSB/LUMEN-(054) DATE: 15 MARCH 2022	JOB DONE: JOB COMPLETION DATE: 31-MAR-2022	 Material: Duplex	3 in Nos	PROJECT: KD PARI END USER:  ROYAL MALAYSIAN NAVY Item Name: Propeller Shaft
		REJECTED DUE TO CRACK UNABLE TO PERFORM THE JOB	 The above is the carbon steel propeller shaft	1 in Nos	Item Name: Intermediate Shaft
		JOB COMPLETION DATE: 09-MAY-2022	 Rudder shaft	2 In Nos	Item Name: Rudder Shaft

COMPLETED JOB DETAILS YEAR 2022

No.	Client Name	Service Job Location	Job Scope	Qty	End User
147	 <p>BANAI ENGINEERING SERVICES & TECHNOLOGY SDN. BHD.</p> <p>PO No. 00-28-105 QM28-313 DATED: 22 MAR 2022</p>	<p>JOB DONE:</p> <p>JOB COMPLETION DATE:</p>	 <p>16" Orbit valve 12:06 pm</p> <p>Material: DUPLEX C/w Hard Chrome Size & Rating: 16" #150 Seat: Metal seated Finding: Coating worn out</p>	2 Nos	
148	 <p>MACROSPEC Sdn Bhd</p> <p>SERVICE ORDER MSB REF. NO: AS22-0021</p>	<p>JOB DONE: Macrospec premises (LABUAN)</p> <p>JOB COMPLETION DATE:</p> <p>Job was not completed</p>	 <p>Material: Duplex F51 c/w Peek Insert Size & Rating 16" #1500 Findings: Scored A & B</p>	1 Nos	<p>Platform: BAKAU valve SDV-2960</p>
149	 <p>Essem Corporation Sdn Bhd</p> <p>P.O No. 20220625-0 Document Date: 15.06.22</p>	<p>JOB DONE: Lumen's Yard</p> <p>JOB COMPLETION DATE: 17-JUN-2022</p>	 <p>Findings: Depth of the score 0.85 mm</p>	1 Nos	<p>Platform: GOBP Tag No. SDV 2061</p> <p>Material: Unknown Size & Rating: 3" #300</p>

COMPLETED JOB DETAILS YEAR 2022

No.	Client Name	Service Job Location	Job Scope	Qty	End User
150	 PETRA RESOURCES SDN BHD YOUR SO No: PI01/4700002826 Your SO Dated: 17/03/2022	JOB DONE: Puchong / SELANGOR JOB COMPLETION DATE: 16-JUN-2022	New enquiry for Gumusut kakap platform 12:35 pm Forwarded 		Material: ALUMINIUM BRONZE Findings: Worn Platform: GUMUSUT KAKAP (GK) JOB NUMBER: LWS22/019
151	Kinetic Cold Technology SDN BHD PO No. KCTSB-PO581-22	JOB DONE: Klang / SELANGOR JOB COMPLETION DATE: 25-08-22	For Brine Pump 	1	Vessel: Portovenere
152	ASMAN KADIR ENGINEERING & FABRICATION SDN BHD PO No. 22-AKEF-PO-VSB-LTS-225	JOB DONE: SUBANG JAYA / SELANGOR JOB COMPLETION DATE: 15-10-22	Project Name: Refurbishment of Mechanical Seals for FSO Puteri Dulang. 	6 units	Petronas Carigali



COMPLETED JOB DETAILS YEAR 2022

No.	Client Name	Service Job Location	Job Scope	Qty	End User
153	 <p>Essem Corporation Sdn Bhd</p> <p>P.O No. 20220991-0 Document Date: 14.09.22</p>	<p>JOB DONE: Puchong / SELANGOR</p> <p>JOB COMPLETION DATE: 20-OCT-2022</p>	<p>1. To fabricate new seat & cage as per sample given (Material: Duplex) 2. Valve Plug to refurbish using selective plating process (Stellite material)</p>  <p>Control Valve</p>	1Nos	TAG No. LCV 3412 Size & Rating: 1 1/2" #150
154	 <p>ORBIT ENGINEERING & MAINTENANCE SERVICES SDN. BHD.</p> <p>Po No: 2563/F332/2022. Po Date 20-OCT-2022</p>	<p>JOB DONE: Kuala Lumpur</p> <p>JOB COMPLETION DATE: 8-DEC-2022</p>	<p>Viton P Oring Seal (Black); H80A; Brand: Krozel P Size: 11mm (w) x 14.5mm (H); Oring size: 790mm (ID) Custom Made</p> 	2 Nos	
155	 <p>JOFFREN OMAR COMPANY SENDIRIAN BERHAD PO No. P07082 DATED: 14-NOV-2022 (Company: based in Brunei)</p>	<p>JOB DONE: Kuala Lumpur</p> <p>JOB COMPLETION DATE: 03-DEC-2022</p>	 <p>To fabricate new shaft</p>	1 Nos	

COMPLETED JOB DETAILS YEAR 2022

No.	Client Name	Service Job Location	Job Scope	Qty	End User
156	 <p>LABUAN SHIPYARD & ENGINEERING SDN BHD</p> <p>GWO No. SC0009741 Order Date: 01/12/2022</p> <p>Project: KD KEDAH (RS/22/029)</p>	<p>JOB DONE: PUCHONG</p> <p>JOB COMPLETION DATE: 16-DEC-2022</p>	 <p>(A) TO REMOVE DAMAGED BABBIT COATING FROM BEARING HOUSING (B) USE WATER JET WITH DEGREASER TO REMOVE OIL FROM INTERNAL OF THE BEARING HOUSING (C) PREHEAT THE BEARING HOUSING TO ENSURE FULLY DRY. (D) SAND BLAST THE BEARING HOUSING INTERNAL SURFACE AREA TO REMOVE RUST, (E) PREHEAT THE BEARING HOUSING & CARRY OUT REBUILD BABBIT IN BEARING HOUSING, (F) PRE COOLING & MACHINING, THE BEARING HOUSING TO SIZE (G) BABBIT BEARING SIZE ID:285MM X L:170MM</p>	4 Units	 <p>ROYAL MALAYSIAN NAVY</p> <p>(RMN)</p>

COMPLETED JOB DETAILS YEAR 2022

No.	Client Name	Service Job Location	Job Scope	Qty	End User
157	 <p>RWNA ENGINEERING SDN BHD</p> <p>PO No. M-22-0435-0003 Order Date: 12/12/2022</p> <p>Project: Offshore Ball valve services for Size: 2inch x 300# and 1inch x 300# at Rwna Yard, Bandar Penawar.</p>	<p align="center">JOB DONE:</p> <p align="center">JOB COMPLETION DATE: 15-DEC-2022</p>	 <p align="center">1 Inch 300#</p>	1 Unit	